



Replace Front Suspension Lower Fore Links

Classification	Campaign Bulletin	Section/Group	31 - Suspension	Country/Region	China
Year	2016	Model	Model S, Model X	Version	All

Bulletin Classification: *This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.*

Condition

Some Model S and Model X vehicles might have been manufactured with front suspension lower fore links that do not conform to Tesla's subjective specifications for strength. In the event of link failure, the tire might contact the wheel arch liner, but the driver can still maintain control of the vehicle.

Correction

Replace both lower fore links.

Correction Description	Correction	Time (Model S)	Time (Model X)
SB-17-31-006 Not Applicable	S011731006	0.00	0.00
Replace LH And RH Front Suspension Lower Fore Links With Updated Parts	S021731006	0.45	0.60

Required Part(s):	Part Number	Description	Quantity
	1041570-00-B	FORE LINK ASSY, LH	1
	1041575-00-B	FORE LINK ASSY, RH	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Manual.

Procedure

Replace the LH and RH front suspension lower fore links (refer to Service Manual procedure 31013402).

Affected VIN(s) Affected Model S and Model X vehicles built between approximately January 19, 2016 and March 6, 2016.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.

