

REPUBLIC OF THE PHILIPPINES

NATIONAL DISASTER RISK REDUCTION AND MANAGEMENT COUNCIL

National Disaster Risk Reduction and Management Center, Camp Aguinaldo, Quezon City, Philippines

NDRRMC UPDATE

SitRep No. 35 re Effects of Magnitude 7.2 Sagbayan, Bohol Earthquake

Releasing Officer:

USEC EDUARDO D. DEL ROSARIO

Executive Director

DATE

03 November 2013, 6:00 AM

Sources: OCD/RDRRMCs V. VII. VIII. IX. X and XI and DSWD-DROMIC, PHIVOLCS, DOTC, DPWH, Deptet, DOH, DILG-Bohol, PNP, AFP, BFP, PCG, PRC and NEA

I. SITUATION OVERVIEW

- An earthquake of tectonic origin with 7.2 magnitude (Ms) occurred in Region VII on 15 October 2013 at about 8:12 AM with an epicentre at Sagbayan, Bohol
- As of 4:00 AM, 03 November 2013, PHIVOLCS recorded 3,198 aftershocks, 94 of which were felt

II. EFFECTS

A. INCIDENTS MONITORED:

- Landslide incidents were reported in the municipalities of Boljoon, Aloguinsa, Argao, Cebu; and in the municipalities of Clarin, Lila, Corella, Balilihan, Alicia, Loboc, Bilar, Cortes, Dimiao, Antequera, Loon, Danao all of Bohol.
- Stampede occurred at Barba Sports Complex in Toledo City and Pinamungahan Auditorium both in Cebu
- At 29 October 2013, a ground subsidence (sink hole) with a very high landslide susceptibility rating was reported by the Mines and Geoscience Bureau (MGB) at Purok 7 and 8 Barangay Poblacion I, Tagbilaran City, Bohol. Houses near the developed sinkhole were advised to initiate readiness and advised to preemptively evacuate

B. CASUALTIES (TAB A) (See SitRep 33)

To date, 222 individuals are reported dead, 976 injured, and 8 are missing

PROVINCE/CITY	TOTAL
Dead - 222	
Cebu	12
Bohol	209
Siquijor	1
Total	222
Injured – 976	
liolio	
Cebu	96
Bohol	877
Siquijor	
Negros Oriental	
Total	976
Missing – 8 (All in Bohol)	
Antequera	1
Clarin	1
Sagbayan	5
Inabanga	1
Total	8

C. AFFECTED POPULATION (TAB B)

- A total of 671,103 families / 3,221,248 persons were affected in 1,527 barangays in 60 municipalities and 6 cities in 6 provinces of Regions VI and VII
- Out of the total affected, <u>71,822 families / 348,507 persons</u> were displaced and served both inside and outside evacuation centers in the Province of Bohol:

Inside 392 Evacuation Centers:

17,203 families / 79,773 persons

Outside Evacuation Centers: 54,619 families / 268,734 persons

D. DAMAGES

Damaged Structures (TAB C)

- A total of <u>73,002 houses</u> were damaged (<u>14,512 totally</u> / <u>58,490 partially</u>) in Bohol, Cebu, Negros Occidental, Negros Oriental, Iloilo, Siguijor and Guimaras
- Seaports, airports, churches, government/public buildings, schools, and hospitals were also damaged in the Provinces of Bohol, Cebu, Iloilo, Negros Occidental, Negros Oriental, Siquijor and Leyte in Regions VI and VII

Damaged Roads and Bridges (TAB D) (See SitRep 33)

- A total of <u>41 bridges</u> were affected of which 38 are already passable and 3 are still not passable, in the Provinces of Bohol, Cebu and Negros Occidental
- A total of <u>18 roads</u> were affected of which <u>16</u> are now passable and <u>2</u> are still not passable in the Provinces of Bohol and Cebu

E. COST OF ASSISTANCE (TAB E)

- As of 6:00 AM, 03 November 2013, The total cost of assistance provided by DSWD, DOH, LGUs and NGOs to Regions VI and VII amounted to <u>PhP71,560,993.47</u>
- Financial assistance was given to the bereaved families of <u>182 dead</u> victims at <u>PhP10,000.00</u> each for a total of <u>PhP1,820,000.00</u>

F. COST OF DAMAGES (TAB F) (See SitRep 33)

A total of PhP2,257,337,182.90 worth of damaged roads, bridges, flood control, school buildings, hospitals, and other public buildings was reported in the Provinces of Cebu (PhP819,051,000.00), Bohol (PhP1,383,159,000.00), Negros Oriental (PhP270,000.00), Siquijor (PhP1,450,000.00), Kabankalan City (PhP1,024,000.00), Bacolod City (PhP11,980,411.67), Candoni (PhP402,771.23), and Capiz (PhP40,000,000.00)

G. STATUS OF LIFELINES

Municipality	No. of Barangays Served	No. of Barangays already energized	Percentage of Power Restored
1. Albuquerque	11	_ 11 _	100%
2. Antequera	21	19	90.48%
3. Baclayon	17	17	100%
4. Balilihan	31	31	100%
5. Batuan	15	15	100%
6. Bilar	19	19	100%

7. Calape	33	29	87.88%
8. Carmen	29	29	100%
9. Catigbjan	21	20	95.24%
10. Clarin	24	24	100%
11. Corella	8	8	100%
12. Cortes	14	13	100%
13. Dauis	12	12	100%
14. Dimiao	35	35	100%
15. Inabanga	50	48	100%
16. Lila	18	18	100%
17. Loay	24	24	100%
18. Loboc	28	28	100%
19. Loon	67	65	97.01%
20. Maribojoc	22	22	100%
21. Panglao	10	10	100%
22. Sagbayan	24	24	100%
23. San Isidro	12	11	100%
24. Sevilla	13	13	100%
25. Sikatuna	10	10	100%
26. Tubigon	34	32	100%

Source: Bohol Electric Cooperative I

- Power supply in Tagbilaran City has been restored on 21 October 2013
- The power supply in the Municipalities of Cortes, Inabanga, San Isidro, and Tubigon in the Province of Bohol has been fully restored as of 9:00 AM, 30 October 3013
- To date, power outage is still being experienced in some barangays in the Municipalities of Antequera, Calape, Catigbian, and Loon

H. STATUS OF SEAPORTS/AIRPORTS OPERATIONS

Airports and seaports in Cebu and Bohol are all operational

I. DECLARATION OF STATE OF CALAMITY

- Province of Bohol was declared under the State of Calamity with Resolution No. 453, s. 2013
- Province of Cebu was declared under the State of Calamity with Resolution No. 1352, s. 2013

III. EMERGENCY MANAGEMENT (TAB G) (See SitRep 33)

Effects of Ms 7.2 Earthquake in Sagbayan, Bohol AFFECTED POPULATION as of 3 November 2013, 6:00 AM

Region/Province/ Mun/City		AFFECTE	D	No. of Evac	Inside Evace	uation Centers		Evacuation nters	TOTAL SERVI	ED - CURREI Outside)
municity	Brgys	Families	Persons	Centers	Families	Persons	Families	Persons	Families	Persons
GRAND TOTAL	1,527	671,103	3,221,248	392	17,203	79,773	54,619	268,734	71,822	348,50
REGION VI (WESTERN VISAYAS)	11	23	99	0		1 NE	4 187	A. 2 . 11	4	V = 1
GUIMARAS	. 1	1	2	0	1 A C	75 74.5	6-14			1 2
JORDAN	1	1	2							
LOILO	1	1	5	0						
ILOILO CITY NEGROS OCCIDENTAL	9	21	92	0						-
IBINALBAGAN	5	14	57	0	- '• '	•		•	-	-
HINOBA-AN (ASIA)	2	3	15						- 1	
PONTEVEDRA	2	4	20							
REGION VII (CENTRAL VISAYAS)	1,516	671,080	3,221,149	392	17,203	79,773	54,619	268,734	71,822	348,5
OHOL	1,109	261,491	1,255,128	390	17,148	79,500	53,245	261,880	70,393	341,3
ALBURQUERQUE	11	2,067	9,921		50	300	150	720	200	
ALICIA	15 16	4,643 3,523	22,285 16,909	6	1,946	9,342	2,371	11,381	4,317	50,
ANTEQUERA	21	3,017	14,481	9	111	504	2,886	13,957	2,997	14,
BACLAYON	17	3,881	18,630				- Chiperical		-	
BALILIHAN BATUAN	31 15	3,573 2,590	17,147 12,431	28	1,292	8,139	1,206	11,008 5,763	3,573 1,206	17,
BIEN UNIDO	15	5,374	25,796				1,400	V.1.03	-	
BILAR	19	3,562	17,098	9	287	1,324	0.700	10 705	287	1,
BUENAVISTA	35 33	5,632 6,280	27,031 30,146	9	1,968	8,898 1,337	2,769 3,825	13,795 20,779	4,737 4,138	22,
CANDIJAY	21	6,051	29,043	111					*	
CARMEN	29	9,079	43,579	22	371	1,896	4,028	18,410	4,399	20,
CATIGBIAN	22 24	4,726 4,228	22,686 20,296	10	697 586	3,147 2,812	3,960 1,009	19,008 5,696	4,657 1,595	22. 8.
CORELLA	8	1,604	7,699	3	12	57	132	634	144	
CORTES	14	3,186	15,294	22			3,059	14,683	3,059	14,
DAGOHOY	15 17	3,931 3,740	18,868 17,952	20	232	933	507	2,535	232 775	3.
DAVIS	12	8,218	39,448		200	1,274	189	945	189	
DIMIAO	35	3,160	15,166				3,160	15,166	3,160	15,
DUERO GARCIA HERNANDEZ	21 30	. 3,663 4,800	17,580 23,038		= 200		38 28	190 140	38 28	
GUINDULMAN	19	6,623	31,789	E.,	-		20	140		
INABANGA	50	9,019	43,291	26	2,145	10,856	435	2,175	2,580	13,
JAGNA JETAFE	33 24	6,785 5,790	32,566 27,788				30 157	150 777	30 157	- 77.1
LILA	18	2,497	11,985				101		107	
LOAY	24	3,388	16,261	17	810	4,000	209	1,045	1,019	5,
LOBOC	28 67	3,398	15,312	3 45	2,851	13,092	1,121 5,052	5,605 24,250	1,130 7,903	37.
LOON	22	8,917 5,870	42,800 28,174	45	2,001	15,092	0,002	24,250	7,005	91.
MARIBOJOC	22	4,269	20,491	35	827	3,428	3,195	16,748	4,022	20,
PANGLAO	10	5,959	28,603 26,887						:	
PILAR PRES, CARLOS P. GARCIA (PITOGO)	21 23	5,602 4,852	23,287				1	400	-	
SAGBAYAN (BORJA)	24	4,186	20,091	18	619	2,462	3,567	17,629	4,186	20,
SAN ISIDRO	12	1,901	9,125	14	348	1,284	1,497	7,503	1,845	8,
SAN MIGUEL SEVILLA	18	4,911 2,176	23,574 10,443	26	202	923	447	1,889	649	2.
SIERRA BULLONES	22	5,145	24,698	1	32	165	100	490	132	-
SIKATUNA	10	1,329	6,380 96,792	8	68 176	326 880	50	240	118	
TAGBILARAN CITY TALIBON	15 25	12,786	61,373	3	176	000			- 70	
TRINIDAD	20	6,008	28,828	2	226	1,085	123	820	349	1,
TUBIGON	34	9,355	44,902	13	702	3,188	5,657	27,714	6,359	30.
VALENCIA	44 35	14,287 5,747	68,578 27,586				7	35	7	1910
EBU	362	404,107	1,939,707	2	. 55	273	1,364	6,806	1,419	7,
ARGAO	45	14,480	69,503				7	24	7	
BOLJOON	11 80	3,131 180,452	15,027 866,171	2	55	273	884	4,420	939	- A
DALAGUETE	33	13,175	63,239					30387		
DUMANJUG	37	9,740	46,754				46.1	0.000	484	2,
MANDAUE	27	69,025	331,320				464	2,320	464	
MINGLANILLA SIBONGA	19 25	23,579 9,092	113,178 43,641				2	12	2	
TABOGON	25	6,880	33,024							
TALISAY	22	41,828	200,772 157,078				. 5	18	5	
TOLEDO	38 45	32,725 5,482	26,314	0			10	48	10	
SIQUIJOR LARENA	23	2,694	12,931	-	17		9	43	9	
MARIA	22	2,788	13,383				1	5	1	

Source: DSWD DROMIC Report No. 57

AFFECTED AREAS	
REGIONS	2
PROVINCES	6
CITIES	6
MUNICIPALITIES	60
BARANGAYS	1,527

EFFECTS of Magnitude 7.2 Earthquake in Sagbayan, Bohol Cost of Assistance As of 03 November 2013, 6:00 AM

Region/Province/Mun/City	DSWD	LGUs	рон	NGOs/Other GOs	TOTAL
GRAND TOTAL	35,624,476.00	3,272,125.60	14,717,311.84	17,947,080.03	71,560,993.47
Region VI		500.00	*	*	500.00
Negros Occidental	E LE DI AN	500.00	1 1 1 1 1 1		500.00
Binalbagan		500.00	Tegrir someonic services		500.0
Region VII	35,624,476.00	3,271,625.60	14,717,311.84	17,947,080.03	71,560,493.47
Bohol 15 control of the section of t	35,624,476.00	1,692,300.00	12,570,360.84	17,431,802.00	67,318,938.84
DOH C.O. (200 cot beds, 15 pcs family tents, 500 pcs Jerry cans, 7 boxes hyposol, assorted drugs and meds, medical supplies, tetracycline ointments, 55 CAMPOLAS Plus kit, 25 pcs Cadaver bags, 30 boxes mineral water, 20,000 aquatabs, 500 hygiene kit, 5,000 pcs T-syringe, 1,500 Sachet ORS, 10,000 caps metronidazole, Cash from National Center for Health Facility Development)			6,463,566.30		6,463,566,30
EAMC (250 amps ATS, 250 amps TT, Anesthesia, gloves and mask, assorted drugs and medicines)			100,941.78		100,941.78
Quirino Memorial Medical Center (assorted drugs, medicines and medical supplies)	1		23,165.50		23,165.50
CHD MM (Assorted medicines, medical and WASH supplies)			556,102.00		556,102.00
CHD III (Assorted medicines and medical supplies)		'	33,000.00		33,000.00
CHD IV-A (assorted medicines, medical supplies)			258,362.73		258,362.73
CHD VI (assorted drugs and medicines, 100 Hygiene kits, 288 bottles Water solution, 2,000 vials of MMR, CASH)			2,312,881.24		2,312,881.24
CHD VII (assorted drugs and medicines)			405,671.30		405,671.30
CHD VIII (Assorted medicines, medical and surgical supplies)			102,682.50		102,682.50
CHD X (assorted medicines, medical and surgical supplies)			200,000.00		200,000.00
POC (Assorted medicines, medical and surgical supplies, external fixators)			457,392.84		457,392.84
JRRMMC (Assorted medicines, Plasterof Paris, wadding sheet, medical supplies, ATS, TT			64,774.68		64,774.68
Batangas Medical Center (assorted medicines, medical supplies)	3.		46,289.00		46,289.00
RMC (Assorted medicines and medical supplies)			23,000.00		23,000.00
TMC (Assorted medicines and medical supplies)			360,470.97		360,470.97
POA (plaster of paris, wadding sheet, elastic bandage)			15,480.00		15,480.00
PMA (Assorted medicines and medical supplies)		7.7	100,000.00		100,000.00
UNFPA (200 pails of Reproductive Health Kit)			170,040.00		170,040.00
WHO (5 Medical Station Tents)			876,540.00		876,540.00
Alburguerque	40,700.00				40,700.00
Alicia	1,129,000.00	150,000.00			1,279,000.00 2,371,900.00
Antequera Baclayon	1,299,200.00 487,600.00	255,150.00		817,550.00	487,600.0
Baciayon	631,300.00			339.400.00	970,700.0
Baluan	1,039,300.00			32,500.00	1,071,800.0
Bilar	495,300.00				495,300.0
Buenavista	634,332,00			278,000.00	912,332.0
Calape	2,358,376.00			1,406,000.00	3,764,376.00
Carmen Caligbian	1,046,240.00 1,929,215.00			1,999,650.00 812,950.00	2,742,165.00
Cangolan	1,555,088.00			743,830.00	2,298,918.00
Corella	49,312.00			26,000.00	75,312.00
Cortes	1,274,900.00			140,054.00	1,414,954.00
Dagohoy	723,700.00			889,754.00	1,613,454.00 876,850.00
Danao	731,400.00			145,450.00	100,000.00
Dauls Dimiao	100,000.00				137,500.00
Garcia-Hernandez	12,520.00				12,520.00
Galda-Heritalidez Getafe	643,900.00			681,500.00	1,325,400.00
Inabanga	3,259,500.00			126,000.00	3,385,500.00
Lila	682,250.00				682,250.00
Loay	169,900.00	67,500.00		294,248.00	531,648.0

Region/Province/Mun/City	DSWD	LGUs	рон	NGOs/Other GOs	TOTAL
Loboc	542,500.00			313,000.00	855,500.00
Loon	2,724,832.00			1,275,200.00	4,000,032.00
Meribojoc	2,419,697.00			997,250.00	3,416,947.00
Panglao	212,500.00				212,500.00
Pilar	196,600.00				196,600.00
Sagbayan	1,864,176.00			1,112,532.00	2,976,708.00
San Isidro	1,275,600.00			149,112.00	1,424,712.00
San Miguel	201,600.00			15,000.00	216,600.00
Sevilla	635,100.00			157,752.00	792,852.00
Sierra Bullones	901,100.00			A-0100ANA 118 C	901,100.00
Sikatuna	734,004.00	308,550.00		5,700.00	1,048,254.00
Trinidad	285,800,00				285,800.00
Tubigon	2,492,934.00	911,100.00		4,664,870.00	8,068,904.00
Tagbilaran City	707,500.00	F. Billion Co.		8,500,00	716,000.00
Cebu		1,579,325.60	2,146,951.00	515,278.03	4,241,554,63
DOH C.O. (10 sets CAMPOLAS, 100 cot beds, 10 family tents, 200 pails of hygiene kit, 100 jerry cans and 144 bots of Hyposol, Cash. Assorted medicines and medical supplies)	- 3		2,146,951.00		2,146,951.00
Dalaguete		3,425.60			3,425.60
Cebu City	12	1,582,000.00		515,278,03	2,077,278.03
Mandaue City		13,900.00			13,900.00

Effects of Magnitude 7.2 Sagbayan, Bohol Earthquake DAMAGED STRUCTURES

As of 03 November 2013, 6:00 AM

REGION	Province/Municipality	TOTALLY	PARTIALLY	TOTAL
		IOIALLI	73,002	TOTAL
	GRAND TOTAL	14 510		73,002
J		14,512	58,490	23
Region	Sub-Total	1	22	21
	NEGROS OCCIDENTAL		3	3
	Hinobaan		14	14
	Binalbagan Pontevedra		4	
VI		0		15.74
	ILOILO Iiloilo City		1	A STATE OF THE PARTY OF THE PAR
	GUIMARAS	1	0	The state of the state of
	Jordan			
Pagion	Sub-Total	14,511	58,468	72,979
Region	BOHOL SUB-10tal	14,480	57,405	71,885
	Alburquerque	60	90	150
	Alicia	884	3,503	4,387
	Antequera	1,166	1,851	3,017
	Balilihan	333	2,596	2,929
	Batuan	55	1,000	1,055
	Bilar	26	302	328
	Buenavista	35	111	146
	Calape	1,142	3,879	5,021
	Carmen	1,177	4,575	5,752
	Catigbian	1,206	3,359	4,565
	Clarin	221	1,137	1,358
	Corella	8	585	593
	Cortes	426	1,461	1,887
	Dagohoy	89	1,645	1,734
	Danao	365	1,609	1,974
	Dauis	2	41	43
	Dimiao	3	144	147
	Duero	40	38	78
	Garcia-Hernandez	1	20	21
VII	Getafe	316	1,518	1,834
A 15	Inabanga	288	2,744	3,032
	Jagna	4	176	180
	Lila	3	185	188
	Loay	171	792	963
	Loboc	116	1,025	1,141
	Loon	1,495	7,422	8,917
	Maribojoc	1,917	1,850	3,767
	Panglao	1	5	6
	Pilar	22	848	870
	Pres. C.P. Garcia	130	1,381	1,511
	Sagbayan	252	737	989
	San Miguel		5	5
	San Isidro	495	1,379	1,874
	Sevilla	80	609	689
	Sierra Bullones	66	1,407	1,473

	Sikatuna	161	586	747
	Talibon	33	20	53
	Tagbilaran City	3	6	9
	Trinidad	14	1,102	1,116
	Tubigon	1,674	5,662	7,336
	CEBU	30	1,055	1,085
	Argao	7		7
	Boljoon	2	11	13
	Dalaguete	3	190	193
	Dumanjug	1		1
	Minglanilla		491	491
3	Sibonga	1	1	2
	Tabogon	4		4
	Cebu City	5	42	47
	Mandaue	3	25	28
	Talisay City	4	295	299
	SIQUIJOR		8	9
	Larena	1	8	9
	Laisila		* *	
SEE		DAM	AGED SEAPORT/A	IRPORT
REGION	Province/Municipality		TATUS	REMARKS
VI	ILOILO			
VI	Iloilo Airport Admin Office	Slight	y Damaged	Resumed Operation
	BOHOL	Co	ollapsed	
	Taghilaran City Port Terminal			7.5
	Tagbilaran City Port Terminal Tagbilaran Airport — Ceiling of the 2nd floor terminal		o Harasa and	Property of Paragraph I are
VII	Tagbilaran City Port Terminal Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower	C	ollapsed	Resumed Operation
VII	Tagbilaran Airport - Ceiling of the 2nd floor terminal building and Airport Tower CEBU			
VII	Tagbilaran Airport - Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port		ollapsed	Resumed Operation Resumed Operation
VII	Tagbilaran Airport - Ceiling of the 2nd floor terminal building and Airport Tower CEBU			
A CHI CONTRACTOR IN	Tagbilaran Airport – Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf	CO	Dilapsed Damaged IAGED IRRIGATION S	Resumed Operation
VII	Tagbilaran Airport - Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality	CO	ollapsed Damaged	Resumed Operation
100 000 000 000 000 000 000 000 000 000	Tagbilaran Airport - Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU	DAN S	Dilapsed Damaged IAGED IRRIGATION S TATUS	Resumed Operation
	Tagbilaran Airport - Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality	DAN S Collapsed its down	Dilapsed Damaged IAGED IRRIGATION S	Resumed Operation
	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam	DAN S Collapsed its dow Canal, Main Canal	Dilapsed Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation needing protection works.	Resumed Operation
	Tagbilaran Airport - Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam	DAM S Collapsed its down Canal, Main Canal Found to have cracks	Damaged Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation	Resumed Operation
	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal	DAN S Collapsed its down Canal, Main Canal Found to have cracks	Damaged Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation needing protection works. Instream aproned in the second secon	Resumed Operation
	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon	DAN S Collapsed its down Canal, Main Canal Found to have cracks	Damaged Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation needing protection works. Instream aprone protection works.	Resumed Operation
100 000 000 000 000 000 000 000 000 000	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC)	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the	Damaged Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation needing protection works. Is; needing some protection works Instream apron, Irrigation needing protection works.	Resumed Operation
A CHI CONTRACTOR IN	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon	Collapsed its down Canal, Main Canal Found to have cracked Leaks were observed assess the Canal Cracks were found in needing p	Damaged Damaged Damaged IAGED IRRIGATION STATUS Instream apron, Irrigation meeding protection works. Is; needing some protection works Ted; needs to excavate to extent of damage. In Main Canal; some portion protection works.	Resumed Operation
A CHI CONTRACTOR IN	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Canal Cracks were found in needing page 1.	Damaged Damaged Damaged IAGED IRRIGATION STATUS Instream apron, Irrigation needing protection works. Is; needing some protection works Ted; needs to excavate to extent of damage. In Main Canal; some portion protection works. Ted; some portion needing	Resumed Operation
A CHI CONSTITUTION	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800)	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing polesks were observed prote	Damaged Damaged IAGED IRRIGATION STATUS Instream apron, Irrigation needing protection works. Is; needing some protection works Instream apron, Irrigation needing protection works. In the company of the company	Resumed Operation
A CHI CONTRACTOR IN	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing potential Cracks were observed for the Cracks were found in control to the Cracks were found in the Cracks were observed for the Cracks were found in th	Damaged Damaged IAGED IRRIGATION STATUS Instream apron, Irrigation meeding protection works. Is; needing some protection works ared; needs to excavate to extent of damage. In Main Canal; some portion motection works. In Main Canal; some portion meeding cition works. In Main Canal; some portion needing cition works. In Main Canal; some portion needing cition works. It is some portion needing cition works.	Resumed Operation
A CHI CONTRACTOR IN	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area)	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing potential Cracks were found in canal Cracks were found in the collapse of the Cracks were found prote	Damaged Damaged IAGED IRRIGATION STATUS Instream apron, Irrigation needing protection works. Is; needing some protection works ared; needs to excavate to extent of damage. In Main Canal; some portion protection works. In Main Canal; some portion protection works. In Main Canal; some portion or protection works. In Main Canal; some portion needing ction works.	Resumed Operation
REGION	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area)	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing protein Cracks were found protein cracks were found protein cracks were observed to the contract of the	Damaged Damaged IAGED IRRIGATION STATUS Instream apron, Irrigation meeding protection works. Is; needing some protection works ared; needs to excavate to extent of damage. In Main Canal; some portion motection works. In Main Canal; some portion meeding cition works. In Main Canal; some portion needing cition works. In Main Canal; some portion needing cition works. It is some portion needing cition works.	Resumed Operation
A CHI CONTRACTOR IN	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area) Lateral D-1, D-2 (Rice area)	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing protein Cracks were observed cracks were found protein the Cracks were observed the Cracks were observed the Cracks were observed assess the Cracks were observed the Cracks were	Damaged Damaged IAGED IRRIGATION STATUS Instream apron, Irrigation needing protection works. Is; needing some protection works Instead and protection works. In Main Canal; some portion needing ction works. In Wall Canal; some portion needing ction works. It was a portion needing ction works. It was a portion needing ction works.	Resumed Operation
REGION	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area) Lateral D-1, D-2 (Rice area) Canal structure (siphon D) BOHOL	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing protein Cracks were found protein Cracks were observed to the collapse of the Cass were observed to the case of the cas	Damaged Damaged IAGED IRRIGATION STATUS Instream apron, Irrigation needing protection works. Is; needing some protection works In the control of the co	Resumed Operation
REGION	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area) Lateral D-1, D-2 (Rice area) Canal structure (siphon D) BOHOL Matabao CIS, Tubigon Dam	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing potenses were observed for the collapse of the collapse	Damaged Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation needing protection works. Is; needing some protection works Ired; needs to excavate to extent of damage. In Main Canal; some portion retection works. Indicated to excavate to extent of damage. In Main Canal; some portion retection works. Indicated to excavate to extent of damage.	Resumed Operation
REGION	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area) Lateral D-1, D-2 (Rice area) Canal structure (siphon D) BOHOL Matabao CIS, Tubigon Dam Cahayag CIS, Tubigon Dam	Collapsed its down Canal, Main Canal Found to have cracked Leaks were observed assess the Cracks were found in needing potes. Cracks were observed cracks were observed to be considered by the collapse on the deportion of Dam collapse.	Damaged Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation needing protection works. Is; needing some protection works Ired; needs to excavate to extent of damage. In Main Canal; some portion retection works. Indicated to excavate to extent of damage. In Main Canal; some portion needing ction works. Indicated to excavate to extent of damage.	Resumed Operation
REGION	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area) Lateral D-1, D-2 (Rice area) Canal structure (siphon D) BOHOL Matabao CIS, Tubigon Dam	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing possess the Cracks were observed cracks were observed cracks were observed cassess the Damages on the deportion of Dam collaps Cracks in tributents	Damaged Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation needing protection works. Is; needing some protection works Ired; needs to excavate to extent of damage. In Main Canal; some portion retection works. Indicated to excavate to extent of damage. In Main Canal; some portion needing ction works. Indicated to excavate to extent of damage. It is the protection and certain of diversion dam. It is the protection and certain of diversion dam. In the protection and certain of diversion dam.	Resumed Operation
REGION	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area) Lateral D-1, D-2 (Rice area) Canal structure (siphon D) BOHOL Matabao CIS, Tubigon Dam Cahayag CIS, Tubigon Dam	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing potes. Leaks were observed protes. Cracks were found in needing potes. Cracks were found protes. Leaks were observed assess the considerable protes. Damages on the deportion of Dam collaps. Cracks in tribute.	Damaged Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation needing protection works. Is; needing some protection works Ired; needs to excavate to extent of damage. In Main Canal; some portion retection works. Indicated to excavate to extent of damage. In Main Canal; some portion needing ction works. Indicated to excavate to extent of damage.	Resumed Operation
REGION	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area) Lateral D-1, D-2 (Rice area) Canal structure (siphon D) BOHOL Matabao CIS, Tubigon Dam Cahayag CIS, Tubigon Dam Ilijan CIS, Tubigon diversion dam	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Canal Reading parties of the Caracks were found in the collapse of the collapse of the caracks are observed assess the Caracks were observed as a carack was a car	Damaged Damaged IAGED IRRIGATION S TATUS Instream apron, Irrigation needing protection works. Is; needing some protection works Ired; needs to excavate to extent of damage. In Main Canal; some portion retection works. Indicated to excavate to extent of damage. In Main Canal; some portion needing ction works. Indicated to excavate to extent of damage. Indicated to excavate to extent of damage. It is the protection and certain of diversion dam. Indicated to landslide. In Main Canal; some portion needing ction works. Indicated to excavate to extent of damage. In Main Canal; some portion needing ction works.	Resumed Operation
REGION	Tagbilaran Airport — Ceiling of the 2nd floor terminal building and Airport Tower CEBU Pasil Fish Port Rhonda wharf Province/Municipality CEBU Owak San Isidro, Asturias Diversion Dam Bug-ot Bogo Tulic CIS Argao Irrigation canal and main canal Dumanjug CIS, Dumanjug canal structure Siphon (Sta.6+700MC) Irrigation Canal (sta. 3+700-3+800) Can-Asujan SRIS, carcar city, Irrigation canal pipeline lateral A (Vege Area) Lateral D-1, D-2 (Rice area) Canal structure (siphon D) BOHOL Matabao CIS, Tubigon Dam Ilijan CIS, Tubigon diversion dam Liboron CIS, Calape dam, Main Canal	Collapsed its down Canal, Main Canal Found to have cracks Leaks were observed assess the Cracks were found in needing poster Cracks were observed prote. Cracks were observed cracks were observed by the Cracks were observed b	Damaged Damaged IAGED IRRIGATION STATUS Instream apron, Irrigation needing protection works. Is; needing some protection works ared; needs to excavate to extent of damage. In Main Canal; some portion protection works. In Main Canal; some portion receding cition works. It is some portion needing cition works. It is some portion and certain followers of damage. It is some portion and certain followers of damage. It is some portion and certain followers of damage. It is some portion and certain followers of damage. It is some portion and certain followers of damage.	Resumed Operation

	Nasig-id SRIS, Zamboanguita main canal (sta. 0+854-0+875)	Siflume collapsed from Mag-abot intake.	
VII	Calango SRIS, Zamboanguita Intake/Dam	Outlet clogged .up due to the entry of debris materials in the damaged trashrack inlet/intake	
REGION	Province/Municipality	DAMAGED FLOOD CONTROL STRUCTURES	
		STATUS REMARKS	
VII	BOHOL		413
	Panangatan River Control	collapsed	
	Shore/Slope Protection Tagbilaran East Road	Totally damaged	
d'alexade	IS STATE NO.	DAMAGED CHURCHES	2 10
REGION	Province/Municipality	REMARKS	
-	ILOILO		178
VI	San Miguel Catholic Church, Poblacion,	partially damaged	
	San Miguel	partially asimages	74
	San Pedro Church in Loboc	Collapsed	4
	Church of Our Lady of the Immaculate Conception in		
	Baclayon	Totally Damaged Façade and Bell Tower	
	Dauis Church and 1 chapel	Partly Damaged	
	Church in Maribojoc	Totally Damaged	
	Church in Loon	Totally Damaged	
	Church in Loay	Partly Damaged	
	Church in Dimiao	Partly Damaged	
	Church in Calape	Partly Damaged	
	Church in Cortes	Partly Damaged	
	Church in Trinidad	Partly Damaged	
	6 Chapels in Inabanga	Totally Damaged	
	Church in Lila	Partly Damaged Partly Damaged	_
	Church in Bilar Church in Tagbilaran City	Partly Damaged Partly Damaged	_
VII	Church in Sikatuna	Partly Damaged	
M	Church in Talibon	Partly Damaged	_
	Church in Clarin	Totally Damaged	_
	Church in Corella	Partly Damaged	
	Church in Panglao	Partly Damaged	
	Church in Tubigon	Totally Damaged	
	Church in Danao and Convent in Brgy Magtangtang	Partly Damaged	
	Church in Carmen	Partly Damaged	_
	Church in Antequera	Partly Damaged	
	Cathedral Church Big Bell Tower	Partly Damaged	
	Iglesia ni Cristo Church	two (2) towers at Mango Avenue collapsed (1 tower with many cracks)	
	Pardo Parish Church	Minor Cracks	
	San Vicente Parish Church, Bogo City	with cracks on the walls	
	Malabuyoc Church	cross damaged/fell	
	Saint Francis of Assissi Parish , Dumanjug	partially collapsed walls	
	Guadalupe Parish Church Basilica Minore del Sto Nino	Collapsed Bell Tower	_
VII	Dalaguete Church	with multiple cracks	_
VII	Brgy. Bonbon, Sinsin, Sudlon 1 Sudlon 2 Chapels	with minor cracks	
	Digy. Dombori, Orient, Court, Court		
REGION	Province/Municipality	DAMAGED GOVERNMENT/PUBLIC BUILDINGS	7.
REGION	Provincermunicipality	REMARKS	
VI	Iloilo City	Minimal cracks	
(0,0)	Metro Iloilo Water District Building	William Gracks	
	BOHOL DSWD-FO VII CIU Building	Partially Damaged	
	Trinidad, Bohol Municipal Building	Collapsed	
	Batuan Municipal Hall	Partially Damaged	
	Dauis Municipal Hall	Partially Damaged	
	Tagbilaran City Hall		
	Buenavista Municipal Hall		
	Danao MPS and Municipal Hall		
	Balilihan Municipal Hall	totally damaged	

	Cortes Municipal Hall	totally damaged
an area	Loon Municipal Hall	totally damaged
VII	Tubigon Municipal Hall	totally damaged
	San Isidro Public Market	totally damaged
	San Isidro MPS Antequera Municipal Hall	totally damaged Partially Damaged
	Panangatan River Control	totally damaged
	Shore/Slope Protection Tagbilaran East Road	
	Lila/Dimiao Section	totally damaged
	BFAR-Provincial Fishery Office, Tagbilaran City	Partially Damaged
	Sagbayan Municipal Hall	totally damaged
	Cebu City Hall	Partially Damaged
	Mandaue City Public Market	Collapsed
	Alcoy New Public Market	cracked walls
	Brgy. Pasil Market of Cebu City	collapsed parapet and gutter
	Sibonga Sports Centrum	leftside wall collapsed
	Philippine Port Authority in Argao	cracked in front
	Fort San Pedro in Cebu City	minor cracks
	DepEd Region VII Building	Damaged
	DTI-Cebu Building	Damaged
	Social Welfare Office in Boljoon	Collapsed
	Boljoon Municipal Hall Talisay City Hall building	Partially Damaged
	Alcoy Municipal Building	cracked glass windows
	Pinamungajan Municipal Building	minor cracks
	Bogo City Hall	cracks on the wall
	Cebu Provincial Capitol Compound (Executive, Legislative, Palace of Justice, BAEX Building, Cebu International Convention Center, CPDRC)	ę.
	Argao Municipal Heritage Bldg.	damaged roofing at the back portion of the building
	Brgy. Bout Taop, Sinsin, Sudlon 1, Sudlon 2, Babag	with minor cracks
	Bonbon Halls Tabogon Municipal Jail	with minor cracks
	rabogon wunicipai saii	With million or dors
REGION	Province/Municipality	DA'MAGED SCHOOLS REMARKS
W. C. 200 SA	The first of the second control of the secon	REMARNS
	Negros Occidental	
	Negros Occidental Negros Occidental National Science High School	Sustained Minor Cracks
	Negros Occidental National Science High School	
		Sustained Minor Cracks Partially Damaged Sustained Minor Cracks
	Negros Occidental National Science High School South Elementary School-Binalbagan	Sustained Minor Cracks Partially Damaged
	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the
	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School-Binalbagan	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office
	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Ilollo Sinamay National High School- Igbaras	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom Sustained minor cracks
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Ilollo Sinamay National High School- Igbaras Mambawi Elementary School, Brgy Sto Angel,	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Ilollo Sinamay National High School- Igbaras Mambawi Elementary School- Igbaras	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom Sustained minor cracks Sustained minor cracks Sustained Minor Cracks with multiple cracks
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Ilollo Sinamay National High School- Igbaras Mambawi Elementary School, Brgy Sto Angel, San Miquel	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom Sustained minor cracks Sustained minor cracks Sustained Minor Cracks
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Ilollo Sinamay National High School- Igbaras Mambawi Elementary School, Brgy Sto Angel, San Miquel Cabatuan National Comprehensive High School	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom Sustained minor cracks Sustained minor cracks Sustained Minor Cracks With multiple cracks One span of rear wall was detached from its column and tilted outside about 50mm Cracked on wall adjacent to column and 2 meter cracked of end parapet wall
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Ilollo Sinamay National High School- Igbaras Mambawi Elementary School- Igbaras Sto. Angel Elementary School, Brgy Sto Angel, San Miquel Cabatuan National Comprehensive High School Tupol Central Elementary School Ban-ag Elementary School, Brgy Ban-ag, Igbaras	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom Sustained minor cracks Sustained minor cracks Sustained Minor Cracks With multiple cracks One span of rear wall was detached from its column and tilted outside about 50mm
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Ilollo Sinamay National High School- Igbaras Mambawi Elementary School- Igbaras Sto. Angel Elementary School, Brgy Sto Angel, San Miquel Cabatuan National Comprehensive High School Tupol Central Elementary School Ban-ag Elementary School, Brgy Ban-ag, Igbaras Siquijor	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom Sustained minor cracks Sustained minor cracks Sustained minor Cracks With multiple cracks One span of rear wall was detached from its column and tilted outside about 50mm Cracked on wall adjacent to column and 2 meter cracked of end parapet wall cracks on floor tiles of H.E. Bldg. and on walls of Grades I, III & IV
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Sinamay National High School- Igbaras Mambawi Elementary School- Igbaras Sto. Angel Elementary School, Brgy Sto Angel, San Miquel Cabatuan National Comprehensive High School Tupol Central Elementary School Ban-ag Elementary School, Brgy Ban-ag, Igbaras Siquijor Leon A. Parami Memorial High School	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom Sustained minor cracks Sustained minor cracks Sustained Minor Cracks With multiple cracks One span of rear wall was detached from its column and tilted outside about 50mm Cracked on wall adjacent to column and 2 meter cracked of end parapet wall Cracks on floor tiles of H.E. Bidg, and on walls of Grades I, III & IV
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Sinamay National High School- Igbaras Mambawi Elementary School- Igbaras Sto. Angel Elementary School, Brgy Sto Angel, San Miquel Cabatuan National Comprehensive High School Tupol Central Elementary School Ban-ag Elementary School, Brgy Ban-ag, Igbaras Siquijor Leon A. Parami Memorial High School	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom Sustained minor cracks Sustained minor cracks Sustained Minor Cracks With multiple cracks One span of rear wall was detached from its column and tilted outside about 50mm Cracked on wall adjacent to column and 2 meter cracked of end parapet wall Cracks on floor tiles of H.E. Bidg, and on walls of Grades I, III & IV with minor cracks with multiple cracks
VI	Negros Occidental National Science High School South Elementary School-Binalbagan Central Phil. State University in Victorias City Fellowship Baptist School- Binalbagan San Teodoro Elem. School- Binalbagan Alternative Learning System-Binalbagan Therese Kinder-Binalbagan Don Angel Yulo Memorial Elem. SchBinalbagan San Juan Elem. School- Binalbagan Sinamay National High School- Igbaras Mambawi Elementary School- Igbaras Sto. Angel Elementary School, Brgy Sto Angel, San Miquel Cabatuan National Comprehensive High School Tupol Central Elementary School Ban-ag Elementary School, Brgy Ban-ag, Igbaras Siquijor Leon A. Parami Memorial High School	Sustained Minor Cracks Partially Damaged Sustained Minor Cracks Partial cracks on flooring, walls of nursery and outer lintel beam of the Principal's Office Cracks on wall of Grade 1 Sec 1 classroom Cracks on wall and window jamb of Community Learning Center, and computer room Cracks on wall Cracks on wall Cracks on wall and beam of Kinder, and Grade 1 Sec. 1 classroom Cracks on wall Grade III classroom Sustained minor cracks Sustained minor cracks Sustained Minor Cracks With multiple cracks One span of rear wall was detached from its column and tilted outside about 50mm Cracked on wall adjacent to column and 2 meter cracked of end parapet wall Cracks on floor tiles of H.E. Bidg, and on walls of Grades I, III & IV

VII

Tagmaonocan Elementary School	with minor cracks
Bohol	
Holy Rosary Academy in Lila	Partially Damaged
Canapnapan Elementary School in Corella	Partially Damaged
Canangcaan Elementary School in Corella	Partially Damaged
Corella High School in Corella	Partially Damaged
Monserat Elementary School in Cortes	Partially Damaged
Bitaugan Primary School	Totally damaged
Lawis Elementary School, Inabanga	Partially Damaged
Ondol Elementary School, Inabanga	Partially Damaged
Sto. Ñino Elementary School, Inabanga	Partially Damaged
Janiod Elementary School, Batuan	Partially Damaged
San Roque High School, Mabini	Partially Damaged
Bugsoc Elementary School, S-Bullones	Partially Damaged
Carmen East Central	Partially Damaged
Ubay CES Sikatuna District (7 Schools)	Partially Damaged Partially Damaged
Albur CES	Partially Damaged
San Miguel TVHS	Partially Damaged
Inabanga South CES	Partially Damaged
Calvario Elementary School, Lila	Partially Damaged
Bonkokan Elementary School, Life	Partially Damaged
Trinidad District (14 schools)	Partially Damaged
Bungahan Elementary School	, willing Damaged
Cambacay Primary School, Batuan	Totally damaged
Ubujam Elementary School, Antequera	Totally damaged
Danao Elementary School, Antequera	Totally damaged
Buyog Primary School, Getafe	Totally damaged
Casica Elementary School, Anda	Totally damaged
Bilangbilangan Elementary School, Bien Unido	Totally damaged
Sacred Heart Academy, Loon	Totally damaged
Tubigon West Central School	Totally damaged
Saint Vincent Institute, Maribujoc	Totally damaged
Panganan High School, Calape	Totally damaged
Cebu	
Dalaguete Provincial High School	multiple cracks
Tudela public schools	
	minor damages
Philippine National High School (Classroom and	Partially Damaged
Philippine National High School (Classroom and Dorm)	Partially Damaged
Philippine National High School (Classroom and Dorm) Lipata Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls and trusses, and cracks in columns damaged exterior walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls and trusses, and cracks in columns damaged exterior walls some exterior walls damaged
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls and trusses, and cracks in columns damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls and trusses, and cracks in columns damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls and trusses, and cracks in columns damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls and trusses, and cracks in columns damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls and trusses, and cracks in columns damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (Comm and academic bulldings Philippine Science High School (Central Visayas	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus)	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on classroom walls, museum and library
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Labangon Elementary School Annex OPRRA Elementary School and Don Vicente Rama	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on classroom walls, museum and library hall collapsed
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Labangon Elementary School Annex OPRRA Elementary School and Don Vicente Rama High School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on classroom walls, museum and library hall collapsed aesthetic damaged
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Labangon Elementary School Annex OPRRA Elementary School and Don Vicente Rama High School Cantipia Integrated School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on classroom walls, museum and library hall collapsed
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Labangon Elementary School Labangon Elementary School Annex OPRRA Elementary School and Don Vicente Rama High School Cantipia Integrated School Brgy Bout Taop, Bonbon, Sinsin, Sudlon 1, Babag	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on classroom walls, museum and library hall collapsed aesthetic damaged
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Labangon Elementary School Labangon Elementary School Annex OPRRA Elementary School and Don Vicente Rama High School Cantipia Integrated School Brgy.Bout Taop, Bonbon, Sinsin, Sudlon 1, Babag schools	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on stage cracks on classroom walls, museum and library hall collapsed aesthetic damaged with large cracks on wall with minor cracks
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Colawin National High School Labangon Elementary School Annex OPRRA Elementary School and Don Vicente Rama High School Cantipia Integrated School Brgy.Bout Taop, Bonbon, Sinsin, Sudlon 1, Babag schools Subangdaku Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on stage cracks on classroom walls, museum and library hall collapsed aesthetic damaged with large cracks on wall with minor cracks with cracks
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Labangon Elementary School Labangon Elementary School Annex OPRRA Elementary School and Don Vicente Rama High School Cantipia Integrated School Brgy.Bout Taop, Bonbon, Sinsin, Sudlon 1, Babag schools Subangdaku Elementary School	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on stage cracks on classroom walls, museum and library hall collapsed aesthetic damaged with large cracks on wall with minor cracks with cracks cracks on walls
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Labangon Elementary School Labangon Elementary School Correct Rama High School Cantipia Integrated School Brgy.Bout Taop, Bonbon, Sinsin, Sudlon 1, Babag schools Subangdaku Elementary School Ibabao Elementary School, Mandaue City	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on stage cracks on classroom walls, museum and library hall collapsed aesthetic damaged with large cracks on wall with minor cracks with cracks cracks on walls cracks on wall
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Labangon Elementary School Labangon Elementary School Correct Rama High School Cantipia Integrated School Brgy.Bout Taop, Bonbon, Sinsin, Sudlon 1, Babag schools Subangdaku Elementary School Ibabao Elementary School, Mandaue City Looc Elementary School, Mandaue City	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on valls cracks on classroom walls, museum and library hall collapsed aesthetic damaged with large cracks on wall with minor cracks with cracks cracks on walls cracks on wall with cracks cracks on walls cracks on wall
Philippine National High School (Classroom and Dorm) Lipata Elementary School Valencia Elementary School Buenavista Elementary School Guadalupe Elementary School Maximo Noel Memorial National High School Kayam Elementary School Napo Elementary School Puesto Elementary School Napo Kalangyawon Elementary School Argao Science High School (dorm and academic buildings Philippine Science High School (Central Visayas Campus) Mandilikit National High School Colawin Elementary School Labangon Elementary School Labangon Elementary School Correct Rama High School Cantipia Integrated School Brgy.Bout Taop, Bonbon, Sinsin, Sudlon 1, Babag schools Subangdaku Elementary School Ibabao Elementary School, Mandaue City	Partially Damaged damaged roof beam, exterior and interior ceiling and walls damaged exterior walls damaged exterior walls damaged exterior walls damaged exterior walls some exterior walls damaged Damaged wooden columns, trusses broken glass windows with cracks on walls cracks on walls damaged ceiling cracks on stage cracks on stage cracks on classroom walls, museum and library hall collapsed aesthetic damaged with large cracks on wall with minor cracks with cracks cracks on walls cracks on wall

REGION	Province/Municipality	DAMAGED HOSPITALS	
		STATUS	REMARKS
VII	CEBU		
	Cebu Doctor's University	Collapsed Roof	
	St. Vincent Hospital - 4th Floor	Cracked	All patients, staff, and employees evacuated
	Cebu City Medical Center	Damaged	Transported patients to Pahina Central Gym and other hospitals
	Sacred Heart Hospital	Minor cracks	
	VSMMC	Minor cracks	
	Mendero Medical Center in Consolacion	with cracks on walls	
VII	BOHOL		
	Congressman Castillo Memorial Hospital	Severely Damaged	Two(2) individuals that were trapped found dead Bodies were retrieved as of 1pm, 16 October 2013 by the Tarsier 117 and MMDA Rescue
	NEGROS ORIENTAL	GIAS TORK	
	Negros Oriental Provincial Hospital	minor cracks	