

NUMBER: 08-037-19 REV. B

GROUP: 08 - Electrical

**DATE:** July 24, 2019

This builetin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Service Bulletin 08-037-19 REV. A, July 22, 2019, which should be removed from your files. All revisions are highlighted with \*\*asterisks\*\* and include additional note in Discussion.

#### SUBJECT:

Rear Window Defroster Inoperable

## **OVERVIEW:**

This bulletin involves inspecting and possibly repairing the terminal of the rear defroster circuit.

# MODELS:

2017 - 2018 (JK) Jeep Wrangler 2018 - Current (JL) Jeep Wrangler

NOTE: This bulletin applies to vehicles within the following markets/countries: North America, EMEA, LATAM and APAC.

NOTE: This bulletin applies to vehicles equipped with Rear Window Defroster (Sales Code GFA).

# SYMPTOM/CONDITION:

Customer may experience the following:

- Rear window defroster is inoperable.
- · Notice a wire(s) hanging from the back glass.

# DISCUSSION:

For these vehicles it is recommended to use a Frost Fighter 2000® Defroster Repair Kit (Fig. 1) and if necessary Mopar #68428688AA, Tab.

NOTE: \*\*FCA US has not determined any other product meets its specifications for electrical tab retention to glass.\*\*



Fig. 1 Frost Fighter 2000 Defroster Repair Kit

NOTE: The flux that is pre-coated on the tab will cause adhesion issues with the epoxy. Remove before applying epoxy to contact point (Fig. 2).



Fig. 2 Rear Defroster Tab

For detailed repair procedure. Refer to the detailed service procedures available in DealerConnect> Service Library under: Service Info> 08 - Electrical / 8G - Heated/Cooled Systems / Heated Glass / Grid, Defogger / Standard Procedure> grid line and terminal repair.

## POLICY:

Information Only

## PART REIMBURSEMENT DETAIL:

Part No:	Description
NPN	Frost Fighter 2000 Defroster Repair Kit

NOTE: This part number is for reimbursement only and will need to be claimed for 1/2 the value of Frost Fighter 2000 defroster repair kit or it will be rejected.