

AIRFOAM INDUSTRIES LTD. TEST REPORT

SCOPE OF WORK

REPORT OF TESTING 100 MM THICK KOROLITE INSULATED METAL PANELS WITH A CENTRE JOINT FOR COMPLIANCE WITH THE APPLICABLE REQUIREMENTS OF THE FOLLOWING CRITERIA: CAN/ULC S102-18, STANDARD METHOD OF TEST FOR SURFACE BURNING CHARACTERISTICS OF BUILDING MATERIALS AND ASSEMBLIES.

REPORT NUMBER

104655432COQ-002 R1

TEST DATE(S)

05/02/21 - 05/02/21

ISSUE DATE

REVISION DATE

05/03/21


05/06/21

PAGES

16

DOCUMENT CONTROL NUMBER

GFT-OP-10c (09/29/20) © 2017 INTERTEK





Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

REPORT ISSUED TO

AIRFOAM INDUSTIRES LTD. 19402 - 56 Avenue Surrey, BC V3S 6K4 CAN

SECTION 1

SCOPE

Intertek Building & Construction (B&C) was contracted by Airfoam Industries Ltd. 19402 - 56 Avenue Surrey, BC V3S 6K4 CAN to perform testing in accordance with CAN/ULC S102-18, Standard Method of Test for Surface Burning Characteristics of Building Materials and Assemblies., on their 100 mm thick Korolite Insulated Metal panels with a centre joint Results obtained are tested values and were secured by using the designated test method(s). Testing was conducted at Intertek Testing Services NA Ltd. (Intertek) test facility at 1500 Brigantine Drive Coquitlam, BC Canada.

Unless differently required, Intertek reports apply the "Simple Acceptance" rule also called "Shared Risk approach," of ILAC-G8:09/2019, Guidelines on Decision Rules and Statements of Conformity.

Intertek B&C will service this report for the entire test record retention period. The test record retention period ends four years after the test date. Test records, such as detailed drawings, datasheets, representative samples of test specimens (where required by Certification or Accreditation bodies), or other pertinent project documentation, will be retained for the entire test record retention period.

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample(s) tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Version: 29 September 2020 Page 2 of 16 GFT-OP-10c



Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

SECTION 2

SUMMARY OF TEST RESULTS

The samples of 100 mm thick Korolite Insulated Metal panels with a centre joint submitted by Airfoam Industries Ltd. were tested in accordance with CAN/ULC S102-18, Standard Method of Test for Surface Burning Characteristics of Building Materials and Assemblies.

The product test results are presented in Section 10 of this report.

For INTERTEK B&C:

COMPLETED BY:	Sean Fewer	REVIEWED BY:	Greg Philp
TITLE:	Technician B&C	TITLE:	Reviewer- B&C
SIGNATURE:	La fair	SIGNATURE:	Gregory Milo
DATE:	05/03/21	DATE:	05/03/21

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample(s) tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Version: 29 September 2020 Page 3 of 16 GFT-OP-10c



Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

SECTION 3

TEST METHOD(S)

The specimens were evaluated in accordance with the following:

CAN/ULC S102-18, Standard Method of Test for Surface Burning Characteristics of Building Materials and Assemblies.

SECTION 4

MATERIAL SOURCE/INSTALLATION

Virtual sampling was conducted by Intertek representative Kareem Abdelghany at the Airfoam Industries Ltd. manufacturing facility located at 19402 - 56 Avenue Surrey, BC CAN on April 19, 2021.

The product was selected in accordance with recognized independent sampling procedures and was received at the Evaluation Center on April 30, 2021.

SECTION 5

EQUIPMENT

ASSET #	DESCRIPTION	MODEL	CAL DUE DATE
WH2189	Photocell	Huygen 856	11/06/21
WH 2190	Smoke Opacity Meter	Huygen	11/06/21
WH 1052	Data Logger	Phidgets DAQ 2020	11/06/21
	Flame Spread Tunnel (S102)	N/A	02/17/22

SECTION 6

LIST OF OFFICIAL OBSERVERS

NAME	COMPANY
Sean Fewer	Intertek B&C



Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

SECTION 7

TEST CALCULATIONS

The results of the tests are expressed by indexes, which compare the characteristics of the sample under tests relative to that of select grade red oak flooring and inorganic-cement board.

(A) Flame Spread Rating:

This index relates to the rate of progression of a flame along a sample in the 7620 mm tunnel. A natural gas flame is applied to the front of the sample at the start of the test and drawn along the sample by a draft kept constant for the duration of the test. An observer notes the progression of the flame front relative to time.

The test apparatus is calibrated such that the flame front for red oak flooring passes out the end of the tunnel in five minutes, thirty seconds (plus or minus 15 seconds).

(B) Smoke Developed:

A photocell is used to measure the amount of light, which is obscured by the smoke passing down the tunnel duct. When the smoke from a burning sample obscures the light beam, the output from the photocell decreases. This decrease with time is recorded and compared to the results obtained for red oak, which is defined to be 100.

SECTION 8

TEST SPECIMEN DESCRIPTION

Upon receipt of the samples at the Intertek Coquitlam laboratory they were placed in a conditioning room where they remained in an atmosphere of 23 \pm 3°C (73.4 \pm 5°F) and 50 \pm 5% relative humidity.

The sample material was identified as 100 mm thick Korolite Insulated Metal panels with 26-gauge pre-painted sheet steel facings and a centre assembled joint typical of field installation. Each sample measured 100 mm thick by 610 mm wide by 2440 mm long and consisted of two 305 mm wide panels connected at the center of the panels and included one line of butyl caulk air barrier within the field assembled joint. Each assembled joint was also lightly caulked on the exterior face with a silicone sealant.

For each trial run, three 610 mm. wide by 2440 mm long pieces of sample material were placed on the upper ledge of the flame spread tunnel to form the required 7315 mm sample length. A layer of 6 mm. thick reinforced cement board was placed over top of the samples, the tunnel lid was lowered into place, and the samples were then tested in accordance with CAN/ULC S102-18.



Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

SECTION 9

TEST RESULTS

(A) Flame Spread

The resultant flame spread ratings are as follows: (Rating rounded to nearest 5)

100 mm thick Korolite Insulated Metal panels with a centre joint	Flame Spread	Flame Spread Rating
Run 1	63	
Run 2	60	65
Run 3	66	

(B) Smoke Developed

The areas beneath the smoke developed curve and the related classifications are as follows: (Classification rounded to nearest 5)

100 mm thick Korolite Insulated Metal panels with a centre joint	Smoke Developed	Smoked Developed Classification
Run 1	294	
Run 2	366	310
Run 3	272	

Observations

During the test runs, surface ignition occurred between 82 and 92 seconds; the flame then began to progress along the sample length until it reached the maximum flame spread.



Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

SECTION 10

CONCLUSION

The samples of 100 mm thick Korolite Insulated Metal panels with an assembled joint typical of field installation submitted by Airfoam Industries Ltd. exhibited the following flame spread characteristics when tested in accordance with CAN/ULC S102-18, Standard Method of Test for Surface Burning Characteristics of Building Materials and Assemblies.

A series of three test runs of material was conducted to conform to the requirements of the National Building Code of Canada.

Sample Material	Flame Spread Rating	Smoke Developed Classification
100 mm thick Korolite Insulated Metal panels with a centre joint	65	310

The conclusions of this test report may be used as part of the requirements for Intertek product certification. Authority to Mark must be issued for a product to become certified.

Version: 29 September 2020 Page 7 of 16 GFT-OP-10c



Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

SECTION 11

TEST DATA (6 PAGES)



Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

	Page 1 of 2
Standard: ULC \$102	
5 (4) (4) (5)	
Lab ID: Intertek Coquitlam Fire Laboratory	
Client: Airfoam Industries	
Date: 02 May 2021	
Project Number: 104655432	
Test Number: 1	
Operator: Sean Fewer	
Specimen ID and Description:	
100mm thick Korolite Insulated Panels with centre Joint	
TEST RESULTS	
FLAMESPREAD INDEX: 63.000	
SMOKE DEVELOPED INDEX: 294.000	
SPECIMEN DATA	
Time to Ignition (sec): 92.279	
Time to Max Flame Spread (min): 5.171	
Maximum Flame Spread (mm): 5.940	
Time to 527 C / 980 F (sec): 6.388	
Max Temperature (deg F or C as per test standard): 675.190	
Time to Max Temperature (sec): 527.279	
Total Fuel Burned (cubic feet): 44.751	
Flame Spread*Time Area (M*min): 33.225	
Smoke Area (%A*min): 457.683	
Unrounded FSI: 62.655	
Unrounded SDI: 294.475	
Officultured 3D1. 254.473	
CALIBRATION DATA	
Time to Ignition of Last Red Oak (sec): 47	
Calibrated Smoke Area (%A*min): 155.423	15 point Heptane average for E84-19b 5 point Red Oak average for S102
	Pr.
Tested by: SF Reviewed by	




Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21





Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

	Pag
Standard: ULC S102	
Lab ID: Intertek Coquitlam Fire Laboratory	
Client: Airfoam Industries	
Date: 02 May 2021	
Project Number: 104655432	
Test Number: 2	
Operator: Sean Fewer	
pecimen ID and Description:	
100mm thick Korolite Insulated Panels with Centre joint	
T DECLUTE	
T RESULTS	
FLAMESPREAD INDEX: 60.000	
SMOKE DEVELOPED INDEX: 366.000	
CIMEN DATA	
Time to Ignition (sec): 81.941	
Time to Max Flame Spread (min): 5.666	
Maximum Flame Spread (mm): 5.940	
Time to 527 C / 980 F (sec): 6.516	
Max Temperature (deg F or C as per test standard): 785.690	
Time to Max Temperature (sec): 570.941	
Total Fuel Burned (cubic feet): 44.587	
Flame Spread*Time Area (M*min): 32.210	
Smoke Area (%A*min): 569.279	
Unrounded FSI: 60.317	
Unrounded FSI: 60.317 Unrounded SDI: 366.276	
Unrounded SDI: 366.276	
Unrounded SDI: 366.276	15 point Heptane average for E84-19b 5 point Red Oak average for S102




Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21





Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

	Page 1 of 2
Standard: ULC S102	
Lab ID: Intertek Coquitlam Fire Laboratory	
Client: Airfoam Industries	
Date: 02 May 2021	
Project Number: 104655432	
Test Number: 3	
Operator: Sean Fewer	
Specimen ID and Description:	
100mm thick Korolite Insulated Panels with centre joint	
TEST RESULTS	
FLAMESPREAD INDEX: 66.000	
SMOKE DEVELOPED INDEX: 272.000	
SPECIMEN DATA	
Time to Ignition (sec): 83.613	
Time to Max Flame Spread (min): 4.894	
Maximum Flame Spread (mm): 5.940	
Time to 527 C / 980 F (sec): 6.144	
Max Temperature (deg F or C as per test standard): 703.790	
Time to Max Temperature (sec): 598.612	
Total Fuel Burned (cubic feet): 44.725	
Flame Spread*Time Area (M*min): 34.587	
Smoke Area (%A*min): 423.153	
Unrounded FSI: 66.095	
Unrounded SDI: 272.258	
5111 5411 4CG 5511 E7 E1250	
CALIBRATION DATA	
Time to Ignition of Last Red Oak (sec): 47	
state of the	15 point Hontone average for 594 10h
Calibrated Smoke Area (%A*min): 155.423	15 point Heptane average for E84-19b 5 point Red Oak average for \$102
commo mandamento acuara Vena del III e e e e e e e e e e e e e e e e e	22 (2000) 200 (2000) (2000) (2000)
Tested by: Sf Reviewed by	
Tested by: Reviewed by	J:




Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21





Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

SECTION 12

PHOTOGRAPHS



Photo No. 1 Pre-Test



Photo No. 2 Post Test



Telephone: 604-520-3321 www.intertek.com/building

TEST REPORT FOR AIRFOAM INDUSTRIES LTD.

Report No.: 104655432COQ-002 R1

Date: 05/03/21

SECTION 13

REVISION LOG

REVISIO	N # DATE	SECTION	REVISION
0	05/03/21	N/A	Original Report Issue
1	05/06/21	2,3,5,6,7	Corrected Product Name Added Narrative on Panel Construction