


TradeReady[®]

Engineering Services: (877) 832-3206 **FLOOR DETAILS**

Technical Services: (888) 437-3244

WARNING

UNDER SERVICE CONDITIONS, ICF WALL MUST BE FREE FROM MOISTURE @ JOIST BEARING, OTHERWISE JOIST CORROSION MAY OCCUR.



<u>ICF - GIRDER BEAM POCKET</u> ClarkDietrich TradeReady Floor Joist System